

KOOS & MIKE USED CARS
 , VANDERBIJLPARK
 Gauteng

DEKRA Vanderbijl Park
 Jorissen Str - 1911
 VANDERBIJLPARK - GT
 016 931 3126



Assignment

| | | | |
|-----------------|-----------------------|---------------------|------------------------|
| Client | KOOS & MIKE USED CARS | Inspection Location | DEKRA Vanderbijl Park |
| Requested Date | 16/07/2024 | | Jorissen Street - 1911 |
| Inspection Date | 16/07/2024 | | Vanderbijlpark - GT |

Vehicle Data

| | | | |
|-----------------|-------------------|-------------------------|------------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | KOOS EN MIKE USED CARS |
| Manufacturer | BMW | Registration Number | CW68026 |
| Model | 3 SERIES | Register Number | VSC501W |
| VIN | WBA3B16090NS61096 | Date Of First Licensing | 10/02/2015 |
| Engine Number | B7411019 | Last COR | |
| Doors | 4 | Last COR | 25/09/2019 |
| Color | WHITE | License Expiry Date | 30/09/2024 |
| Year Model | 2015 | Power / Displacement | 135kW/1997cc |
| Km Reading | 205,812 KM | Paint Finish | C - COMMON |
| Cab / Body Type | SEDAN | Fuel | PETROL |
| | | Transmission | AUTOMATIC |

Vehicle Options & Accessories

Items

6 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; CD changer; Cruise control; El. mirrors; Fog lights; Front armrest; Headlamp washer; Leather interior; Leather steering wheel; Multifunction steering wheel; On-board computer; Park sensor; Radio cd; Rain sensor; Traction control system;

VEHICLE INSPECTION

Interior

No negative smell was detected in the vehicle interior. Seats with minor signs of wear including discoloration / fading / stains. Interior trim and/or roof lining and/or carpets show minor signs of wear and/or minor staining. Dashboard with normal signs of wear. The cluster without any defects. The functions of heating and ventilation are without detectable defects. The function of control units and/or instrument cluster is without detectable faults. The testable functions of the air condition is without deficiencies. The function of the electric windows is defect-free. Defects were detected on the electric seats and/or seat heaters. Service due and the service record incomplete.

Exterior

The rims show no defects which affect the function. The mechanics of doors / bonnet / tailgate are defect-free. No residual traces of damage repair were detected. The vehicle shows normal signs of wear & tear according to age and milage. Vehicle Body with several dents or scratches or corrosion (edge corrosion / surface corroded). Minor paint damage to the primer were detected. The glass panes show minor signs of wear and scratches. Hang-on parts (grill, bumpers, mirrors, antennas, strips, etc.) show minor damages. The spare wheel tread depth is below 1mm, damaged or missing. The tire tread depth is more than 1 mm. The tires are in good condition

Engine, Gearbox, Drivetrain

The engine-oil level is normal with no visible signs of contamination. The cooling system is without testable defects. The coolant level is normal. The engine shows traces of oil sweat. The gearbox and/or drive shaft show traces of oil sweat. The exhaust system shows signs of damages and/or rust, the functionality is not affected. During the road test no deficiencies were detected on gearshift, clutch, automatic transmissions. During the road test no atypical noises were detected. Minor defects were detected on engine, gearbox, drivetrain - the functionality is not affected.

Axles, Undercarriage

The break fluid level is normal with no visible signs of contamination. Brake pads and discs show signs of wear & tear. The brake pads and/or discs show signs of wear & tear. The undercarriage with minor damages. Minor defects on axles an / or suspension were detected - the functionality is not affected.

Brakes

Brake Test Results

Brake efficiency tested during road test.

| | Left | Right | Axle Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | 2.73 | 2.88 | - | |
| Rear | 2.44 | 2.36 | - | |
| Emergency / Parking | 2.13 | 2.28 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|------------|------------------|-------------|---------|-------|-----------------|------------------|
| Front Left | 225/50R17 | 94W | Michelin | Primacy | V | 3122 | 6 mm |
| Front Right | 225/50R17 | 94W | Michelin | Primacy | V | 5122 | 6 mm |
| Rear Left | 225/50ZR17 | 98Y | Tracmax | Privilo | V | 5123 | 8 mm |
| Rear Right | 225/50ZR17 | 98Y | Tracmax | Privilo | V | 1224 | 8 mm |

* Tyre Legend: V=Virgin, R=Recap

Tyre tread depth minimum 1mm according to National Road Traffic Act 93 of 1996.

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Vehicle Dirty

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.NO ELECTRICAL ADJUSTABLE SEATS=INSUFFICIENT.NO SPAREWHEEL=INSUFFICIENT.

Body • Exterior: Vehicle has signs of small dents, chips and scratches on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Petrus Mapongwane Makhubo

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

ROADWORTHY RELEVANT DAMAGES

| Damage | Repair Way | Repair Cost | % | Pro Rata |
|---|---------------------|-------------|-----|----------|
| During the time of test,no defects were detected. | Roadworthy Relevant | 0 | 0 % | 0 |
| Total: | | 0 | | 0 |

| Car | | Car | |
|-----------------|------------|------------------|-------------------|
| Name/No: | | License pl. no.: | 1340120 |
| Year: | | Year: | 2012 |
| Zip code, city: | | Ins. no.: | |
| Telephone: | | Manufacturer: | BMW |
| Test date: | 2024/07/16 | Model: | 116i |
| Test time: | 09:22 | VIN: | WBA3B16090NS61096 |

| SIDE-SLIP TEST | |
|----------------|--------|
| Front axle | -2 m/s |
| Rear axle | 8 m/s |

| BRAKE TEST | | | | | | | | | |
|-------------------|------------------|-------|-----------|-------------|---------------------|-------------|------------|------------|------------|
| Brake test (km/h) | Brake force (kN) | | Diff. (%) | Quality (%) | Deceleration (m/s²) | Weight (kg) | Factor (%) | Pulse (ms) | Pulse (ms) |
| | Left | Right | | | | | | | |
| FA | 0.17 | 0.20 | 2.30 | 3.80 | 3 | 65 | 42 | 367 | 917 |
| RA | 0.17 | 0.19 | 2.44 | 2.34 | 3.30 | 3 | 69 | 63 | 818 |
| PS | 0.17 | 0.19 | 2.43 | 2.28 | 4.41 | 7 | --- | --- | --- |

| Brake evaluation | | | |
|---------------------------|---------|----------------|---------|
| Max. brake force (kN) | 0.41 | Inbalance (%) | 0 |
| Service brake system (PS) | 4.1 | Disc. rate (%) | 65 |
| Pushing brake system (PS) | 4.1 | Disc. rate (%) | 27 |
| Static weight | 1677 kg | Dynamic weight | 1689 kg |


| LIMIT VALUES BRAKE TESTER | |
|-----------------------------|---------------------------|
| Deceleration (m/s²) | FA: 40%, RA: 41%, PS: 44% |
| Deceleration (%) | FA: 12%, RA: 10%, PS: 12% |
| Brake force difference (kN) | FA: 30%, RA: 18% |
| Brake force difference (PS) | 30% |

| TOTAL EVALUATION | |
|------------------|--------|
| Test result | Passed |


Brake test report




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



90 DEGREE FRONT




90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD




NO LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Engine covered by belly plate



Chassis from the front



Chassis from the rear



Oil filler cap



ADDITIONAL 9